

# EXHIBIT #1



OUR SERVICE DEPT. HOURS:  
MONDAY THRU FRIDAY  
7:30 A.M. TO 6:30 P.M.  
SATURDAY  
8:00 A.M. TO 5:00 P.M.  
B.A.R. # REG ARD 009143



**STAR MAZDA**  
"the Star Supercenter"

1401 SOUTH BRAND BLVD.  
GLENDALE, CALIFORNIA 91204  
www.starautogroup.com



Phone: (818) 247-1803  
Service Direct: (818) 502-1434  
Fax: (818) 248-0593  
E.P.A. # CAD 981445158

CELL: 323-403-6616

CUSTOMER NO. <b>61057</b>	ADVISOR <b>WILFREDO RIVERA</b>	PAG NO. <b>939</b>	INVOICE DATE <b>07/09/10</b>	INVOICE NO. <b>MACS628179</b>
CHRISTINA PASCHAL 4312 BRUNSWICK AVE LOS ANGELES, CA 90039 christina.castellan@gmail.com	LABOR RATE <b>6FVK365</b>	MILEAGE <b>53,938</b>	COLOR <b>SILVER/</b>	STOCK NO.
	YEAR / MAKE / MODEL <b>04/MAZDA/RX-8/4DR CPE AT</b>		DELIVERY DATE	DELIVERY MILES
	VEHICLE ID NO. <b>J M 1 F E 1 7 N X 4 0 1 2 3 9 2 7</b>		SELLING DEALER NO.	PRODUCTION DATE
	P.T.E. NO.	R.O. NO.	R.O. DATE <b>07/08/10</b>	
RESIDENCE PHONE	BUSINESS PHONE	COMMENTS	MO: 53938	

LABOR & PARTS  
J# 1 06MAZFC CHECK ENGINE LIGHT TECH(S):250 WARRANTY  
TOWED IN CUST STS ENGINE SLOW CRANKS BUT WON'T START

UPON VEHICLE INSPECTION FOUND ENGINE FLOODED  
NOTE ENGINE MUST BE FULLY WARM UP BEFORE IS TURNED OFF.  
PERFORM ENGINE DECARBONIZING PER PROGRAM 01015108  
APPROVED BY MAZDA  
ENGINE MUST BE FULLY WARM UP BEFORE IS TURNED OFF.

PARTS	QTY	FP NUMBER	DESCRIPTION	UNIT PRICE	WARRANTY
JOB # 1	1	0000-77-AB6	ZOOM POWER		
				JOB # 1 TOTAL PARTS	0.00

JOB # 1 TOTAL LABOR & PARTS 0.00

J# 2+22MAZMF MIS FIRES TECH(S):250 WARRANTY  
TOWED IN CUST STS ENGINE CRANKS BUT START UP  
ELECTRONIC ENGINE DIAGNOSIS INDICATES A ENGINE MISFIRE  
FAULTY CODES P3004 AND P3002 RANDOM COIL MISFIRE  
REPLACED ALL IGNITION COILS AND RESET COMPUTER TO  
CORRECT CONCERN REPAIRS APPROVED BY MAZDA

PARTS	QTY	FP NUMBER	DESCRIPTION	UNIT PRICE	WARRANTY
JOB # 2	4	N3H1-18-100B-9U	IGNITION C		
				JOB # 2 TOTAL PARTS	0.00

JOB # 2 TOTAL LABOR & PARTS 0.00

J# 3+03MAZBRKG BRAKES/GREEN TECH(S):250  
PERFORM BRAKE INSPECTION FRONT AND REAR AS PER FULL CIRCLE  
INSPECTION  
COMPLETED BRAKE INSPECTION AS PER FULL CIRCLE PROCESS,  
ADVISED CLIENT BRAKES ARE GREEN STATUS OK.

PARTS	QTY	FP NUMBER	DESCRIPTION	UNIT PRICE	WARRANTY
				JOB # 3 TOTAL PARTS	0.00

JOB # 3 TOTAL LABOR & PARTS 0.00

J# 4+23MAZBATTG BATT/PASSED TECH(S):250  
PERFORMED A BATTERY CHECK  
BATTERY IS NEW, REPLACED ON THIS REPAIRS

PARTS	QTY	FP NUMBER	DESCRIPTION	UNIT PRICE	WARRANTY
				JOB # 4 TOTAL PARTS	0.00

JOB # 4 TOTAL LABOR & PARTS 0.00

J# 5+25MAZTIRR TIRES/RED TECH(S):250  
PERFORM TIRE INSPECTION AS PER FULL CIRCLE PROCESS,  
ADVISED CLIENT TIRES ARE RED STATUS IMMEDIATE ATTENTION  
REQUIRED

JOB # 5 TOTAL LABOR & PARTS 0.00